



A CAUTION

Spring force has been set at medium level by the factory. When adjusting, do NOT exceed the maximum number of turns allowed for each direction.

For STRONG direction: Max. 4 turns For WEAK direction: Max. 4 turns

Warning: Failure to above instructions will cause serious damage against the device. The unit may no longer work properly and will need to be replaced.

Example:

- Wire will no longer get retracted into the case.
- Shackle or wire ring will be badly damaged/deformed.

